


Part # BT-SPYRA

13-0927

PARTS




A




B



C




D



6Vac 500 mA Adapter



E

1




remove black
cap and throw
away

2



**LED Operation**

1. Charge internal battery using Adaptor (E). Battery lasts 6 - 8 hours on a full 8 hour charge.
2. Push SPEED button to regulate color phasing between Slow, Medium and Fast.
3. Push ON/OFF button to turn LEDs on and off.
4. Push HOLD button to pause LEDs on specific color.

3



4



Press down on table
top and lift lever to
activate hydraulic
pole